

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

PCN#19-087**NOTIFICATION DATE: October 10, 2019****MODEL(S) AFFECTED:**

| |
|----------------------|
| DPLB-2025A0+ |
| DPLB-6585A0+ |
| DPLB-8510A04+ |
| DPLB-8510A05+ |

EXTENT OF CHANGE:

Plugged PTH in signal pads of PCB is used to eliminate solder bleeding. And additional securing done for air coils to avoid leg lift.

EFFECT OF CHANGE:

- No change to **FIT** (dimension) or **FUNCTION** (performance)
- Change in **FORM** (appearance) additional securing will be seen in the affected models.

REASON FOR CHANGE:

To avoid solder bleeding in signal pads of the units and avoid detachment of air coil legs

EFFECTIVE DATE OF CHANGE:

Immediate

ATTACHMENTS:

n/a

QUESTIONS?**[PLEASE CONTACT US.](#)**