Typical Performance Curves

LOWPASS INSERTION LOSS
INPUT POWER = 0 dBm



LOWPASS RETURN LOSS
INPUT POWER = 0 dBm



HIGHPASS INSERTION LOSS
INPUT POWER = 0 dBm



HIGHPASS RETURN LOSS
INPUT POWER = 0 dBm



CROSS OVER ISOLATION
INPUT POWER = 0 dBm



COMMON PORT RETURN LOSS
INPUT POWER = 0 dBm