Typical Performance Curves

LOW PASS INSERTION LOSS vs. TEMPERATURE
INPUT POWER = 0 dBm



HIGH PASS INSERTION LOSS vs. TEMPERATURE
INPUT POWER = 0 dBm



LOW PASS RETURN LOSS vs. TEMPERATURE
INPUT POWER = 0 dBm



HIGH PASS RETURN LOSS vs. TEMPERATURE
INPUT POWER = 0 dBm



COMMON PORT vs. TEMPERATURE
INPUT POWER = 0 dBm