Typical Performance Curves

LOW PASS INSERTION LOSS
INPUT POWER = 0 dBm



HIGH PASS INSERTION LOSS
INPUT POWER = 0 dBm



LOW PASS RETURN LOSS
INPUT POWER = 0 dBm



HIGH PASS RETURN LOSS
INPUT POWER = 0 dBm



COMMON PORT RETURN LOSS
INPUT POWER = 0 dBm