## *Typical Performance Curves*

**LOW PASS INSERTION LOSS**
INPUT POWER = 0 dBm




**LOW PASS RETURN LOSS**
INPUT POWER = 0 dBm




**HIGH PASS INSERTION LOSS**
INPUT POWER = 0 dBm




**HIGH PASS RETURN LOSS**
INPUT POWER = 0 dBm




**COMMON PORT RETURN LOSS**
INPUT POWER = 0 dBm




**CROSS OVER ISOLATION**
INPUT POWER = 0 dBm