Typical Performance Curves

INSERTION LOSS
INPUT POWER = 0 dBm



INPUT RETURN LOSS
INPUT POWER = 0 dBm



OUTPUT RETURN LOSS
INPUT POWER = 0 dBm