*Typical Performance Curves*

**INSERTION LOSS vs. TEMPERATURE**
INPUT POWER = 0 dBm




**INSERTION LOSS vs. TEMPERATURE**
INPUT POWER = 0 dBm (Passband)




**INPUT RETURN LOSS vs. TEMPERATURE**
INPUT POWER = 0 dBm




**INPUT RETURN LOSS vs. TEMPERATURE**
INPUT POWER = 0 dBm (Passband)




**OUTPUT RETURN LOSS vs. TEMPERATURE**
INPUT POWER = 0 dBm




**OUTPUT RETURN LOSS vs. TEMPERATURE**
INPUT POWER = 0 dBm (Passband)