Typical Performance Curves

INSERTION LOSS vs. FREQUENCY (Full band)
INPUT POWER = -10 dBm, Temperature = +25°C



INSERTION LOSS vs. FREQUENCY (Pass band)
INPUT POWER = -10 dBm, Temperature = +25°C



INPUT RETURN LOSS vs. FREQUENCY (Full band)
INPUT POWER = -10 dBm, Temperature = +25°C



INPUT RETURN LOSS vs. FREQUENCY (Pass band)
INPUT POWER = -10 dBm, Temperature = +25°C



OUTPUT RETURN LOSS vs. FREQUENCY (Full band)
INPUT POWER = -10 dBm, Temperature = +25°C



OUTPUT RETURN LOSS vs. FREQUENCY (Pass band)
INPUT POWER = -10 dBm, Temperature = +25°C



GROUP DELAY vs. FREQUENCY (Full band)
INPUT POWER = -10 dBm, Temperature = +25°C



GROUP DELAY vs. FREQUENCY (Pass band)
INPUT POWER = -10 dBm, Temperature = +25°C