Typical Performance Curves

INSERTION (Full Band)
INPUT POWER = -10 dBm



INSERTION (Pass Band)
INPUT POWER = -10 dBm



INPUT VSWR (Full Band)
INPUT POWER = -10 dBm



INPUT VSWR (Pass Band)
INPUT POWER = -10 dBm



OUTPUT VSWR (Full Band)
INPUT POWER = -10 dBm



OUTPUT VSWR (Pass Band)
INPUT POWER = -10 dBm