*Typical Performance Curves*

**INSERTION LOSS vs. TEMPERATURE (Full band)**
INPUT POWER = -25 dBm




**INSERTION LOSS vs. TEMPERATURE (Pass band)**
INPUT POWER = -25 dBm




**INPUT RETURN LOSS vs. TEMPERATURE (Full band)**
INPUT POWER = -25 dBm




**INPUT RETURN LOSS vs. TEMPERATURE (Pass band)**
INPUT POWER = -25 dBm




**OUTPUT RETURN LOSS vs. TEMPERATURE (Full band)**
INPUT POWER = -25 dBm




**OUTPUT RETURN LOSS vs. TEMPERATURE (Pass band)**
INPUT POWER = -25 dBm




**GROUP DELAY vs. TEMPERATURE (Full band)**
**INPUT POWER = -25 dBm**




**GROUP DELAY vs. TEMPERATURE (Pass band)**
**INPUT POWER = -25 dBm**