



## Typical Performance Curves


**LOW PASS INSERTION LOSS vs. TEMPERATURE**  
INPUT POWER = 0 dBm




**HIGH PASS INSERTION LOSS vs. TEMPERATURE**  
INPUT POWER = 0 dBm



**HIGH PASS RETURN LOSS vs. TEMPERATURE**  
INPUT POWER = 0 dBm



**HIGH PASS RETURN LOSS vs. TEMPERATURE**  
INPUT POWER = 0 dBm



**COMMON PORT vs. TEMPERATURE**  
INPUT POWER = 0 dBm

