

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

PCN22-068

NOTIFICATION DATE: September 20, 2022

MODELS AFFECTED

See attached list of part numbers affected

EXTENT OF CHANGE:

Evaluation of performance based on relocation of key component supplier

EFFECT OF CHANGE:

No change to FIT (Dimension), FORM (Appearance) or FUNCTION (Performance)

REASON FOR CHANGE:

Requalification and verification of performance based on supplier relocation. Any change, if found, will be advised separately

EFFECTIVE DATE OF CHANGE:

Immediate.

ATTACHMENTS:

QUESTIONS?

[PLEASE CONTACT US.](#)

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

List of Affected Models				
1GC2-4225	CMA-5043+	RCAT-00+	TB-668-02+	TB-MAC-12GL+
1GC2-4242	CMA-5043-2+	RCAT-01+	TB-668-03+	TB-MAC-24LH+
1GN3-4003	CMA-545+	RCAT-02+	TB-668-04+	TB-MAC-24MH+
1GN3-4202	CMA-545G1+	RCAT-02-1+	TB-668-05+	TB-MAC-42+
1GN3-4203	CMA-545G1-2+	RCAT-02-2+	TB-668-06+	TB-MAC-42LH+
1GN3-4204	CMA-545G1-4	RCAT-02-5+	TB-668-07+	TB-MAC-42MH+
1GN3-4205	CMA-62+	RCAT-03+	TB-668-08+	TB-MAC-60+
1GN3-4207	CMA-63+	RCAT-04+	TB-668-09+	TB-MAC-60MH+
1GN3-4209	CMA-81+	RCAT-05+	TB-668-10+	TB-MAC-85+
1GN3-4211	CMA-82+	RCAT-06+	TB-668-12+	TB-RMK-3-391HP+
1GN3-4212	CMA-82-1+	RCAT-07+	TB-668-15+	TB-SYM-R252HW+
1GX1-4224	CMA-83LN+	RCAT-08+	TB-668-20+	TB-TUF-R1MHSM+
ADE-R11XLH+	CMA-83LN-1+	RCAT-09+	TB-668-30+	TB-TUF-R3LHSM+
ADE-R12MH+	CMA-84+	RCAT-10+	TB-679+	TB-VSAT-0+
ADE-R18WLH+	CSWA2-63DR+	RCAT-12+	TB-756+	TB-VSAT-2+
ADE-R1LH+	CSWA2-63DR-4+	RCAT-15+	TB-757+	TB-VSAT-3+
ADE-R1MHW+	CSWA2-63DR-5+	RCAT-20+	TB-758+	TB-VSAT-5+
ADE-R20LH+	HJK-R28H-1	RCAT-20-1+	TB-759+	TUF-3HSM-3+
ADE-R25MH-1	HPA-0660-50+	RCAT-30+	TB-829-103+	TUF-R1MHSM+
ADE-R272MH+	HPG-13	RMK-3-32HP-2+	TB-829-81+	TUF-R3LHSM+
ADE-R2ASKLH+	HPG-13+	RMK-3-391HP+	TB-829-82+	VLM-83-2W-1+
ADE-R30WLH+	HS-4PD-TESTER	SSG-4000HP	TB-829-84+	VLM-83-2W-S+
ADE-R35LH+	HTEST-4PD-S	SSG-4000LH	TB-862+	VSAT-0+
ADE-R3GLH+	HTEST-5P	SSG-6000RC	TB-988-103+	VSAT-0-1+
ADE-R5LH+	JCIQ-156M-1+	SYM-83H-1+	TB-994+	VSAT-0-2+
ADE-R5LH-2+	JCIQ-400M-2+	SYM-R252HW+	TB-ADE-R11XLH+	VSAT-2+
ADE-R5LH-3+	K1-RCAT+	SYM-R252HW-1+	TB-ADE-R12MH+	VSAT-2-1+
ADE-R6LH+	LAVI-222LH-1	TB-1GN3-4202	TB-ADE-R1LH+	VSAT-2-2+
ADE-R901LH+	LAVI-222LH-1QA	TB-1GN3-4203	TB-ADE-R1MHW+	VSAT-3+
ADEX-R10LH+	LRMS-1HJ-1R	TB-1GN3-4205	TB-ADE-R20LH+	VSAT3-02+
CLM-63-2W-1+	MAC-12G+	TB-1GN3-4207	TB-ADE-R272MH+	VSAT-3-1+
CLM-83-2W+	MAC-12GL+	TB-1GN3-4209	TB-ADE-R2ASKLH+	VSAT-5+
CLM-83-2W-10DVU	MAC-24LH+	TB-1GX1-4224+	TB-ADE-R30WLH+	VSAT-5-1+
CLM-83-2W-12DVU	MAC-24MH+	TB-461+	TB-ADE-R35LH+	VSAT-5-2+
CLM-83-2W-13+	MAC-42+	TB-631+	TB-ADE-R3GLH+	ZFSWA2-63DR+
CLM-83-2W-3+	MAC-42-2DVU	TB-656-62+	TB-ADE-R5LH+	ZFSWA2-63DR-1+
CLM-83-2W-8+	MAC-42LH+	TB-656-63+	TB-ADE-R6LH+	ZFSWA2-63DRB+
CLM-83-2W-9+	MAC-42MH+	TB-656-81+	TB-ADE-R901LH+	ZFSWA2-63DRB-1+
CMA-103+	MAC-42MH-3+	TB-656-82+	TB-ADEX-R10LH+	ZHL-0660-8X+
CMA-162LN+	MAC-60+	TB-656-84+	TB-CMA-183L+	ZHL-4080-10X+
CMA-183L+	MAC-60MH+	TB-668-00+	TB-CMA-183LE+	ZT-186
CMA-252LN+	MAC-85+	TB-668-01+	TB-MAC-12G+	