

## PRODUCT CHANGE NOTICE

### PCN Form (D4-E000-73)

**PCN#16-015****NOTIFICATION DATE: March 16, 2016****MODEL(S) AFFECTED:**

DAT-31575-PN+	DAT-3175-PN+	DAT-15575-PN+
DAT-31575-PP+	DAT-3175-PP+	DAT-15575-PP+
DAT-31575-SN+	DAT-3175-SN+	DAT-15575-SN+
DAT-31575-SP+	DAT-3175-SP+	DAT-15575-SP+

**EXTENT OF CHANGE:**

Models listed are identified as LAST TIME BUY status based on discontinuation and availability of replacement.

**EFFECT OF CHANGE:**

Listed model is not recommended for new customer designs and will be discontinued.  
Last time buys are being offered to existing customers in order to extend availability.  
Recommended replacement to be introduced with "A" suffix to part number to distinguish them.

**REASON FOR CHANGE:**

End of life notification received from supplier of critical internal component

**EFFECTIVE DATE OF CHANGE:**

Immediate

**DELIVERY:**

Availability dependent on stock condition.

**ATTACHMENTS:**

List of Affected Models

**QUESTIONS?****[PLEASE CONTACT US.](#)****ISO 9001 CERTIFIED**



## PRODUCT CHANGE NOTICE

### PCN Form (D4-E000-73)

Attachment to **PCN#16-015**

<b>** List of Affected Models **</b>	
<b>Original Model:</b>	<b>Replacement Model:</b>
DAT-31575-PN+	DAT-31575A-PN+
DAT-31575-PP+	DAT-31575A-PP+
DAT-31575-SN+	DAT-31575A-SN+
DAT-31575-SP+	DAT-31575A-SP+
DAT-3175-PN+	DAT-3175A-PN+
DAT-3175-PP+	DAT-3175A-PP+
DAT-3175-SN+	DAT-3175A-SN+
DAT-3175-SP+	DAT-3175A-SP+
DAT-15575-PN+	DAT-15575A-PN+
DAT-15575-PP+	DAT-15575A-PP+
DAT-15575-SN+	DAT-15575A-SN+
DAT-15575-SP+	DAT-15575A-SP+