


Typical Performance Curves


INSERTION LOSS vs. TEMPERATURE (Full Band)

INPUT POWER = -10 dBm




INSERTION LOSS vs. TEMPERATURE (Pass Band)

INPUT POWER = -10 dBm




INPUT VSWR vs. TEMPERATURE (Full Band)

INPUT POWER = -10 dBm




INPUT VSWR vs. TEMPERATURE (Pass Band)

INPUT POWER = -10 dBm



OUTPUT VSWR vs. TEMPERATURE (Full Band)

INPUT POWER = -10 dBm



OUTPUT VSWR vs. TEMPERATURE (Pass Band)

INPUT POWER = -10 dBm

