

PRODUCT CHANGE NOTICE PCN Form (D4-E000-73)

EOL/PCN#23-009

NOTIFICATION DATE: March 9, 2023

MODELS AFFECTED

See list of models on page 2 and 3

EXTENT OF CHANGE:

Obsolescence of critical supplied components with no known Form-Fit-Functional replacement.

EFFECT OF CHANGE:

End of life notification received from supplier of critical internal components. Mini-Circuits will initiate efforts in redesigning and finding alternate solutions. We are confident in our success to develop Form/Fit/Functional replacement however at this time do not have a time line for completion. Therefore, Last Time Buy is highly encouraged.

REASON FOR CHANGE:

Discontinuation of Supplier material

EFFECTIVE DATE OF CHANGE:

Last Time Buy available for orders to be placed by no later than April 28, 2023 with shipments completed by April 28, 2024. Last Time Buy may be limited in quantities and timing. Mini-Circuits will continue supporting existing customers' needs for as long as stock of the original materials exists. Contact your Account Manager or sales@minicircuits.com for availability

ATTACHMENTS:

List of affected models

QUESTIONS?

[PLEASE CONTACT US.](#)

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

List of Affected Models				
ADE-R11XLH+	CMA-162LN-2+	CMA-84+	RCAT-02+	TUF-R5SM+
ADE-R18WLH+	CMA-183A+	CMA-84-1+	RCAT-02-2+	VLM-83-2W-S+
ADE-R20LH+	CMA-183L+	CSWA2-63DR+	RCAT-02-4F	ZFSWA2-63DR+
ADE-R272MH+	CMA-252LN+	CSWA2-63DR-4+	RCAT-03+	ZFSWA2-63DRB+
ADE-R2ASKLH+	CMA-252LN-1F	HJK-R28H-1	RCAT-03-3F	ZFSWA2-63DRB-1+
ADE-R30WLH+	CMA-5043+	HPA-0660-50+	RCAT-04+	ZHL-0660-8X+
ADE-R35LH+	CMA-5043-2+	HPG-13	RCAT-05+	ZHL-4080-10X+
ADE-R3GLH+	CMA-5043-2+	HPG-13+	RCAT-06+	ZT-186
ADE-R5LH+	CMA-545+	HS-4PD-TESTER	RCAT-07+	TB-461+
ADE-R5LH-2+	CMA-545-3	HTEST-4PD-S	RCAT-08+	TB-631+
ADE-R5LH-3+	CMA-545G1+	HTEST-5P	RCAT-09+	TB-656-62+
ADE-R6LH+	CMA-545G1-2+	JCIQ-156D-1+	RCAT-10+	TB-656-63+
ADE-R901LH+	CMA-545G1-2+	JCIQ-156M-1+	RCAT-12+	TB-656-81+
ADEX-R10LH+	CMA-545G1-4	JCIQ-400D-1+	RCAT-15+	TB-656-82+
CLM-63-2W-1+	CMA-62+	JCIQ-400M-2+	RCAT-20+	TB-656-84+
CLM-83-2W+	CMA-62-1+	LAVI-222LH-1	RCAT-30+	TB-668-10+
CLM-83-2W-10DVU	CMA-62-1+/GRPC	LAVI-222LH-1	RMK-3-32HP-2+	TB-668-20+
CLM-83-2W-10F	CMA-62-1+/GRPD	LAVI-222LH-1QA	RMK-3-391HP+	TB-668-30+
CLM-83-2W-11F	CMA-62-3F	LAVI-222LH-1QA	RMK-5-751-5+	TB-679+
CLM-83-2W-12DVU	CMA-63+	MIQA-21D+	SSG-4000HP	TB-756+
CLM-83-2W-12F	CMA-63-1+	MIQA-21D-1+	SSG-4000LH	TB-757+
CLM-83-2W-3+	CMA-63-1+/GRPC	MWJ-J5-14	SSG-6000RC	TB-758+
CLM-83-2W-3+	CMA-63-1+/GRPD	MWJ-J5-14QA	SYM-83H-1+	TB-759+
CLM-83-2W-5RGA+	CMA-63-2F	MWJ-J5-15	SYM-R252HW+	TB-829-82+
CLM-83-2W-6+	CMA-81+	MWJ-J5-15QA	SYM-R252HW-1+	TB-988-103+
CLM-83-2W-7+	CMA-82+	PWR-8PW-RC	TUF-3HSM-3+	TB-994+
CLM-83-2W-9+	CMA-82-1+	RCAT-00+	TUF-R1MHSM+	TB-ADE-R11X+
CMA-103+	CMA-83LN+	RCAT-00-2F	TUF-R1SM+	TB-ADE-R12MH+
CMA-103-1F	CMA-83LN-1+	RCAT-01+	TUF-R3LHSM+	TB-ADE-R1L+
CMA-162LN+	CMA-83LN-2F	RCAT-01-2F	TUF-R3SM+	TB-ADE-R20LH+

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

List of Affected Models

TB-ADE-R272MH+	TB-668-03+	TB-829-103+	TB-ADE-R2ASK+	TB-ADEX-R10+
TB-ADE-R30WLH+	TB-668-04+	TB-829-81+	TB-ADE-R2ASKLH+	TB-CMA-183LE+
TB-ADE-R5LH+	TB-668-05+	TB-829-84+	TB-ADE-R30W+	TB-RMK-3-391HP+
TB-ADEX-R10LH+	TB-668-06+	TB-979+	TB-ADE-R35LH+	TB-SYM-R252HW+
TB-CMA-183L+	TB-668-07+	TB-ADE-R1+	TB-ADE-R3GLH+	TB-TUF-R1MHSM+
TB-TUF-R3SM+	TB-668-08+	TB-ADE-R11XLH+	TB-ADE-R6+	TB-TUF-R1SM+
TB-668-00+	TB-668-09+	TB-ADE-R1LH+	TB-ADE-R6LH+	TB-TUF-R3LHSM+
TB-668-01+	TB-668-12+	TB-ADE-R1MHW+	TB-ADE-R901+	TB-TUF-R5SM+
TB-668-02+	TB-668-15+	TB-ADE-R20+	TB-ADE-R901LH+	