

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

EOL/PCN#25-050

NOTIFICATION DATE: July 17, 2025

MODELS AFFECTED:

Original Model Number	Replacement Model Number	Replacement Guide
HPA-25W-272+	HPA-20M2G7025+	AN-60-135
ZHL-20W-202-S+	ZHL-10M2G0020+	AN-60-127
ZHL-20W-202X-S+	ZHL-10M2G0020X+	AN-60-127
ZHL-5W-202-S+	ZHL-10M2G0005+	AN-60-127
ZHL-5W-202X-S+	ZHL-10M2G0005X+	AN-60-127
ZHL-10W-202-S+	ZHL-10M2G0010+	AN-60-126
ZHL-10W-202X-S+	ZHL-10M2G0010X+	AN-60-126
ZHL-30W-252-S+	ZHL-0G62G5030+	AN-60-124
ZHL-30W-252X-S+	ZHL-0G62G5030X+	AN-60-124
ZHL-30W-252-4+		AN-60-124
ZHL-30W-252X-3+		AN-60-124
ZHL-2-12+	ZHL-10M1G21W0+	AN-60-131
ZHL-2-12X+	ZHL-10M1G21W0X+	AN-60-131
ZHL-2-8-S+	ZHL-10M1G01W1+	AN-60-125
ZHL-2-8X-S+	ZHL-10M1G01W1X+	AN-60-125
ZHL-2-S+	ZHL-10M1G01W0+	AN-60-130
ZHL-2X-S+	ZHL-10M1G01W0x+	AN-60-130
ZHL-25W-272+	ZHL-20M2G7025+	AN-60-132
ZHL-25W-272X+	ZHL-20M2G7025X+	AN-60-132

EXTENT OF CHANGE:

Introduction of redesigned versions under new Part Numbers.

EFFECT OF CHANGE:

Please refer to Replacement Guides listed in the table above for detailed comparison.

REASON FOR CHANGE:

Redesign of Amplifier series to replace internal material due to Supplier obsolescence.

EFFECTIVE DATE OF CHANGE:

Immediate

QUESTIONS?

[PLEASE CONTACT US.](#)