

## PRODUCT CHANGE NOTICE

### PCN Form (D4-E000-73)

**EOL/PCN#26-027****NOTIFICATION DATE: August 6, 2026****MODELS AFFECTED:**

| Original Model Number | Replacement Model Number | Replacement Guide         |
|-----------------------|--------------------------|---------------------------|
| ZHL-10W-2GX+          | ZHL-0G82G0010X+          | <a href="#">AN-60-137</a> |
| ZHL-10W-2G+           | ZHL-0G82G0010+           | <a href="#">AN-60-137</a> |
| ZHL-10W-2G-1+         | No change                | <a href="#">AN-60-137</a> |
| ZHL-100W-272X+        | ZHL-0G72G7100X+          | <a href="#">AN-60-138</a> |
| ZHL-100W-272+         | ZHL-0G72G7100+           | <a href="#">AN-60-138</a> |
| ZQL-2700MLNW+         | ZQL-2G22G70W3+           | <a href="#">AN-60-139</a> |
| TVA-R5-13A+           | HPA-0M51G02W5+           | <a href="#">AN-60-140</a> |

**EXTENT OF CHANGE:**

Introduction of redesigned versions under new Part Numbers.

**EFFECT OF CHANGE:**

Please refer to Replacement Guides listed in the table above for detailed comparison.

**REASON FOR CHANGE:**

Redesign of Amplifier series to replace internal material due to Supplier obsolescence.

**EFFECTIVE DATE OF CHANGE:**

Immediate

**QUESTIONS?****[PLEASE CONTACT US.](#)**