

# PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

D	(1)	N.T	· 114	10			
М		V	#(	19	-(1	П	"/

**NOTIFICATION DATE: April 24, 2009** 

Refer to Procedure: D3-E040

# **MODELS FAMILY AFFECTED:**

BP, GP, SP, WP (Power Splitters)
D1, D2 (Directional Couplers)
See Attached List for Specific Models

# **EXTENT OF CHANGE:**

Device marking from ink to Laser

# **EFFECT OF CHANGE:**

Minor impact on form (appearance). No impact on fit or function.

### **REASON FOR CHANGE:**

Improved manufacturability

#### **EFFECTIVE DATE OF CHANGE:**

May 1, 2009

# **DELIVERY:**

Delivery of either <u>ink</u> or <u>laser</u> marked units may be shipped, until ink marked units are depleted from stock.

#### **ATTACHMENTS:**

List for Specific Models

QUESTIONS?

PLEASE CONTACT US.



# PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

PCN #09-007

# **List of Models Affected**

<b>BP-Series</b>
BP2C
BP2C+
BP2C1+
BP2G
BP2G+
BP2G1+
BP2P
BP2P+
BP2P1+
BP2U+
BP2U1+
BP4C
BP4C+
BP4C1+
BP4P
BP4P+
BP4P1+
BP4U+
BP4U1+

D-Series
D20C
D20C+
D19G
D18P
D18P+
D17I
D17I+

GP-Series
GP2S+
GP2S1+
GP2X+
GP2X1+
GP2Y+
GP2Y1+

SP-Series
SP-2C+
SP-2C1+
SP-2G+
SP-2G1+
SP-2L+
SP-2P+
SP-2P1+
SP-2U+
SP-2U1+
SP-2U2+
SP-2W+
SP-2W1+

WP-Series
WP4A+
WP4C+
WP4C1+
WP4F+
WP4F1+
WP4G+
WP4G1+
WP4L+
WP4M+
WP4N+
WP4P+
WP4P1+
WP4R+
WP4R1+
WP4S+
WP4U+
WP4U1+
WP4W+
WP4W1+