

PRODUCT CHANGE NOTICE PCN Form (D4-E000-73)

PCN#18-014

NOTIFICATION DATE: February 12, 2018

MODEL(S) AFFECTED:

KBA, KC2, KSX2, MACA, MBA, MCA1, SBA, SIM (see attached list for specific models)

EXTENT OF CHANGE:

Change of epoxy dome glob-top material and dimensions

EFFECT OF CHANGE:

No change to Fit or Function. Change to dome material and dimensions.

REASON FOR CHANGE:

Supplier (HYSOL) discontinuation of existing epoxy and replacement with recommended and qualified alternate formulation.

EFFECTIVE DATE OF CHANGE:

Immediate

ATTACHMENTS:

List of affected models.

QUESTIONS?

[PLEASE CONTACT US.](#)

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

Attachment to: PCN#18-014

** List of Affected Models **				
KBA-20	MBA-18MH+	MCA1-24MH+	MCA1T-12G+	SIM-43H+
KBA-20+	MBA-25L+	MCA1-42+	MCA1T-12GL+	SIM-43LH+
KBA-40	MBA-25LH+	MCA1-42LH+	MCA1T-24+	SIM-43MH+
KBA-40+	MBA-25MH	MCA1-42MH+	MCA1T-24LH+	SIM-63LH+
KC2-11+	MBA-25MH+	MCA1-60+	SBA-2-14	SIM-722MH+
KC2-19+	MBA-26	MCA1-60LH+	SBA-2-14+	SIM-73L+
KC2-36+	MBA-35L	MCA1-60MH+	SBA-2-18	SIM-762H+
KC2-50+	MBA-35LH	MCA1-80H+	SBA-2-18+	SIM-792LH+
KSX2-14+	MBA-35MH	MCA1-80LH+	SBA-2-20	SIM-83+
KSX2-24+	MBA-42	MCA1-80MH+	SBA-2-20+	SIM-83LH+
KSX2-442+	MBA-56MH	MCA1-85+	SBA-2-22	SIM-852MH+
KSX2-722+	MBA-591	MCA1-85L+	SBA-2-22+	
MACA-242H+	MBA-591+	MCA1T-24MH+	SIM-U432H+	
MBA-10L	MBA-591L	MCA1T-42+	SIM-U63+	
MBA-10VL	MBA-591L+	MCA1T-42LH+	SIM-U712H+	
MBA-12+	MBA-671	MCA1T-42MH+	SIM-U742MH+	
MBA-12H	MBA-671+	MCA1T-60+	SIM-14+	
MBA-12MH	MBA-9	MCA1T-60LH+	SIM-14H+	
MBA-15L	MBA-9H	MCA1T-60MH+	SIM-14LH+	
MBA-15L+	MBA-9MH	MCA1T-80H+	SIM-153+	
MBA-15LH+	MCA1-113H+	MCA1T-80LH+	SIM-153LH+	
MBA-15MH+	MCA1-12G+	MCA1T-80MH+	SIM-153MH+	
MBA-18L	MCA1-12GL+	MCA1T-85+	SIM-193H+	
MBA-18LH+	MCA1-24+	MCA1T-85L+	SIM-24MH+	
MBA-18MH	MCA1-24LH+	MCA1T-113H+	SIM-43+	

ISO 9001 CERTIFIED