

PRODUCT CHANGE NOTICE PCN Form (D4-E000-73)

PCN#19-093

NOTIFICATION DATE: October 17, 2019

MODEL(S) AFFECTED:

DPLC-2025A0+	DPLC-8510A0+	DPLC-2025AC-2+
DPLC-2025A0M+	DPLC-8510A01+	PLBDC9-122752+
DPLC-6585A0+	DPLC-8510A01M+	PLX204-258DC1+
DPLC-6585A0M+	DPLC-8510AC-2+	PLX85-102DC1+

EXTENT OF CHANGE:

Additional securing done for air coils to avoid leg lift.

EFFECT OF CHANGE:

- No change to **FIT** (dimension) or **FUNCTION** (performance)
- Change in **FORM** (appearance) additional securing will be seen in the affected models.

REASON FOR CHANGE:

To avoid detachment of air coil legs

EFFECTIVE DATE OF CHANGE:

Immediate

ATTACHMENTS:

n/a

QUESTIONS?

[PLEASE CONTACT US.](#)