

**PRODUCT CHANGE NOTICE**  
**PCN Form (D4-E000-73)****PCN#20-023**


NOTIFICATION DATE: June 8, 2020

**MODEL(S) AFFECTED:**

<b>BPF-300A-1+</b>	<b>BPF-1000A-1+</b>
<b>BPF-V300+</b>	<b>BPF-V1000+</b>

**EXTENT OF CHANGE:**

To improve the cover securing process, changed the securing position from longer side to shorter side.

**EFFECT OF CHANGE:**No change to **FIT** (dimension) or **FUNCTION** (performance).  
Change to **FORM** (appearance) due to Epoxy position changed.**REASON FOR CHANGE:**

Improved cover securing.

**EFFECTIVE DATE OF CHANGE:**

Immediate

**ATTACHMENTS:**

N/A

QUESTIONS?

[PLEASE CONTACT US.](#)

07/15/2020: PCN revised to update photos

AS9100 ISO9001 ISO14001 Certified to QMS and EMS