

PRODUCT CHANGE NOTICE PCN Form (D4-E000-73)

PCN#17-055

NOTIFICATION DATE: August 29, 2017

MODEL(S) AFFECTED:

ROS-1660+

EXTENT OF CHANGE:

1. Replacement of supplied transistor based on discontinuation of supply with alternate, qualified components.
2. Change of internal component values to optimize replacement parts

EFFECT OF CHANGE:

No change in FIT or FORM

No change in specifications, no degradation in performance, improvement in Harmonics per table below:

Parameters	Original Performance	New Performance	Catalog Spec
2 nd Harmonic	-23.56 to -21.68 dBc	-28.11 to -25.18 dBc	-19 dBc Typ
3 rd Harmonic	-29.07 to -28.55 dBc	-33.86 to -31.64 dBc	-10 dBc Max

No change in internal or external layout.

REASON FOR CHANGE:

Obsolescence of supplied components

EFFECTIVE DATE OF CHANGE:

Immediate, pending stock depletion

Last date code of old design for ROS-1660+ **Date Code 1612**

ATTACHMENTS:

Data available to support the change

QUESTIONS?

[PLEASE CONTACT US.](#)