



Typical Performance Curves


INSERTION LOSS vs. TEMPERATURE (Full band)
INPUT POWER = -25 dBm




INSERTION LOSS vs. TEMPERATURE (Pass band)
INPUT POWER = -25 dBm




INPUT RETURN LOSS vs. TEMPERATURE (Full band)
INPUT POWER = -25 dBm




INPUT RETURN LOSS vs. TEMPERATURE (Pass band)
INPUT POWER = -25 dBm




OUTPUT RETURN LOSS vs. TEMPERATURE (Full band)
INPUT POWER = -25 dBm



OUTPUT RETURN LOSS vs. TEMPERATURE (Pass band)
INPUT POWER = -25 dBm



GROUP DELAY vs. TEMPERATURE (Full band)
INPUT POWER = -25 dBm



GROUP DELAY vs. TEMPERATURE (Pass band)
INPUT POWER = -25 dBm

