

**PRODUCT CHANGE NOTICE**  
PCN Form (D4-E000-73)

**PCN#07-010-1**

**NOTIFICATION DATE: December 5, 2007**

**MODEL AFFECTED:**

**KC2, KBA, MBA, MCA1, SIM Series**

*(See Attached Listing of Specific Models)*

**EXTENT OF CHANGE:**

Storage & Handling per MSL3 for models with date codes older than 0743

**EFFECT OF CHANGE:**

Application of J-STD-020 & J-STD-033 requirement for special pre-conditioning (Pre-Bake) and packaging (including desiccants) prior to customer assembly per MSL3.

**REASON FOR CHANGE:**

To conform to industry standard for process control for MSL3 component

**EFFECTIVE DATE OF CHANGE:**

Immediate

Parts with date codes newer than 0743 will not be packed per MSL3

**QUESTIONS?**

**PLEASE CONTACT US.**

## PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

### List of Models for **PCN#07-010-1**

KBA -Series	MBA -Series	MCA1 -Series	SIM -Series
KBA-20	MBA-10L	MCA1-12G+	SIM-14+
KBA-20+	MBA-10L+	MCA1-12GL+	SIM-14H+
KBA-40	MBA-12	MCA1-24+	SIM-14LH+
KBA-40+	MBA-12+	MCA1-24LH+	SIM-43+
	MBA-15L	MCA1-24MH+	SIM-43H+
	MBA-15L+	MCA1-42+	SIM-43LH+
	MBA-15LH	MCA1-42LH+	SIM-43MH+
	MBA-15LH+	MCA1-42MH+	SIM-63LH+
	MBA-15MH	MCA1-60+	SIM-73L+
	MBA-15MH+	MCA1-60LH+	SIM-83+
	MBA-18LH	MCA1-60MH+	SIM-83LH+
	MBA-18LH+	MCA1-80H+	SIM-153+
	MBA-25L	MCA1-80LH+	SIM-153LH+
	MBA-25L+	MCA1-80MH+	SIM-153MH+
	MBA-25LH	MCA1-85+	SIM-722MH+
	MBA-25LH+	MCA1-85L+	SIM-762H+
	MBA-25MH	MCA1-113H+	SIM-792LH+
	MBA-25MH+		SIM-U432H+
	MBA-591		SIM-U63+
	MBA-591+		SIM-U712H+
	MBA-591L		SIM-U742MH+
	MBA-591L+		
	MBA-671		
	MBA-671+		