

PRODUCT CHANGE NOTICE PCN Form (D4-E000-73)

PCN# 15-008

NOTIFICATION DATE: March 3, 2015

MODEL(S) AFFECTED:

ROS-3250-519+
ZX95-3250+

EXTENT OF CHANGE:

1. Replacement of supplied transistor and varactor diode based on discontinuation of supply with alternate, qualified components.
2. Slight changes of additional internal components to support item 1 and repeat historical performance.

EFFECT OF CHANGE:

No change in FIT or FORM

Slight change in Function - performance differs from original performance as follows:

Parameters	Original Performance	Current Performance	Current Spec
Second Harmonic	-25.88 to -18.42	-23.53 to -16.94	-20 dBc Typ, -12 dBc Max
Third Harmonic	-64.09 to -34.33	-61.02 to -30.56	

No addition or removal of components.

REASON FOR CHANGE:

1. Obsolescence of supplied transistor
2. Obsolescence of supplied varactor diode.

EFFECTIVE DATE OF CHANGE:

Immediate

ATTACHMENTS:

Data available to support the change
See updated spec for change in typical harmonics

QUESTIONS?

PLEASE CONTACT US.

ISO 9001 CERTIFIED