

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

PCN#19-050**NOTIFICATION DATE: April 26, 2019****MODEL(S) AFFECTED:**

| | | |
|------------|------------|-----------|
| SKY-53R+ | SKY-53MHR+ | SKY60-LH+ |
| SKY-53LHR+ | SKY-60+ | SKY-60MH+ |

EXTENT OF CHANGE:

Temporary change to substrate material and appearance based on supplier lot variation

EFFECT OF CHANGE:

- No change to FIT (dimensions) or FUNCTION (performance)
- Change to FORM (appearance)
- Elimination of green solder mask on the bottom of the device for some lots.
- No change to datasheet specifications

REASON FOR CHANGE:

- Supplier lot variation
- Substrate is a stacked PCB, with the bottom layer only used to stiffen and build to the required thickness. No other functionality.

EFFECTIVE DATE OF CHANGE:

Immediate

ATTACHMENTS:

Photos

QUESTIONS?**[PLEASE CONTACT US.](#)**

*08/26/19- Rev. A: PCN revised
to include additional models.*


PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

Attachment to PCN: **PCN#19-050**



Top view
(Picture - 1)



Bottom View
(Picture - 2)