

## PRODUCT CHANGE NOTICE PCN Form (D4-E000-73)

**PCN#18-085**

**NOTIFICATION DATE: August 1, 2018**

**MODEL(S) AFFECTED:**

**ADE, HJK, LAVI, MWJ, SYM, & ZHJK** (*See attached list for specific models*)

**EXTENT OF CHANGE:**

Replacement of internal quad die with alternate, equivalent qualified die

**EFFECT OF CHANGE:**

- No change in FIT or FORM or FUNCTION
- Samples available for performance evaluation

**REASON FOR CHANGE:**

Obsolescence of supplied die and replacement with equivalent.

**EFFECTIVE DATE OF CHANGE:**

Immediate

**ATTACHMENTS:**

N/A

**QUESTIONS?**

**[PLEASE CONTACT US.](#)**

## PRODUCT CHANGE NOTICE

### PCN Form (D4-E000-73)

Attachment to **PCN#18-085**

<b>** List of Affected Models **</b>			
ADE-12MH-9+	HJK-272H+	LAVI-17VH-1+	LAVI-427H-1+
ADE-132FH+	HJK-272MH+	LAVI-182VH-1+	LAVI-452VH+
ADE-132FMH+	HJK-351H+	LAVI-182VH-2+	LAVI-452VH-3+
ADE-201FMH+	HJK-372H+	LAVI-185H-11+	LAVI-470H-1+
ADE-2UFMH-1+	HJK-3H-10+	LAVI-18GVH-1+	LAVI-470VH-1+
ADE-611MH-1+	HJK-3H-8+	LAVI-1920H-1+	LAVI-491H-1+
ADE-611MHU-1+	HJK-412H+	LAVI-22VH+	LAVI-711H+
ADE-851FH+	HJK-421H+	LAVI-22VH-1+	LAVI-960H-1+
ADE-851FLH+	HJK-442LH-1+	LAVI-22VH-6+	LAVI-971VH+
ADE-92+	HJK-461H-1+	LAVI-23VH+	LAVI-9VH-1+
ADE-92LH+	HJK-462H-1+	LAVI-23VH-2+	LAVI-U182H+
ADE-92MH+	HJK-481H+	LAVI-23VH-3+	LAVI-U252VH+
HJK-121VH-1+	HJK-540H-1+	LAVI-2400-1+	MWJ-J5-1+
HJK-122H-2+	HJK-551H+	LAVI-252H+	MWJ-J5-11+
HJK-13MH-3+	HJK-621H-1+	LAVI-252VH+	MWJ-J5-12
HJK-151MH+	HJK-824H-1+	LAVI-25VH+	MWJ-J5-13+
HJK-1651H+	HJK-9H-92-1+	LAVI-2600VH-1+	MWJ-J5-2+
HJK-172H+	HJK-U151H+	LAVI-2VH+	MWJ-J5-9+
HJK-212H+	HJK-U232H+	LAVI-33VH-31+	MWJ-J7-1+
HJK-251H+	K1-LAVI+	LAVI-33VH-5+	PE4140-DW+
HJK-251HR-1+	LAVI-10VH+	LAVI-362VH+	SYM-352H-1+
HJK-260H-1+	LAVI-1160VH-1+	LAVI-362VH-3	SYM-452H-2+
HJK-261H+	LAVI-142VH-2+	LAVI-362VH-4+	SYM-462VH-1+
HJK-262H-1+	LAVI-17VH+	LAVI-422H-3+	ZHJK-925H-1+